

Under Review Notification

Raised By: Will Monterroza

Product #: D169-841

Date: 2016.12.21

Product Name: AW169 Cable Cutters

Part Number (D-Part and 9-Digit) (D3535-11/-25, D206-642-143, etc.)	Drawing or Document & Current Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review		
D169-841-015	IIN D169-841, rev D	Y	Y	Y	Y	Y	Y	Y	16-692	
D4842-041	Lower Cutter Assembly	Y	Y	Y	Y	Y	Y	N	16-692	Update part by removing 0.005" from base face
D4842-3	LH Lower Cutter Body	Y	Y	Y	Y	Y	Y	N	16-692	Update part by removing 0.005" from base face
D4842-4	RH Lower Cutter Body	Y	Y	Y	Y	Y	Y	N	16-692	Update part by removing 0.005" from base face

Description of Issue:

The Lower cable cutter will not install onto the aircraft base. Request by Leonardo for width of base does not match existing product design. Dart asked Leonardo to provide original definition but have not provided it yet. In order to continue shipments, the LH Lower cutter body D4842-3 and RH Lower cutter body D4842-4 that make part of the D4842-041 need to be revised to shave 0.005" off the base interface

**** Note that this change needs to be communicated to Leonardo by Dart Quality through a Proposal for Change Request and it must be approved by Leonardo prior to implementing ****

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Production Planners

Program Manager

Technical Support

Purchasing Manager